

PAT Report Fail For all Sites and Locations

CLIENT DETAILS	
Company Name:	Fabrication Company
Address:	Address 1 Address 2



DETAIL OF CONTRACTOR RESPONSIBLE FOR TESTING	
Company Name:	Testsafe Ltd
Address:	Bretby Business Park Ashby Road Burton on Trent DE15 0YZ
Telephone:	01283 229873
Fax:	
Email:	sales@test-safe.co.uk
Cert Number:	
Order Number:	
File Name:	Fabrication Co_TS00000.PAT
Signature:	

APPLIANCE DETAILS AND TEST RESULTS

Key
P = PASS / F = FAIL / S = SKIP (or test not applicable)

Appliance Id	Appliance Description	Test Date	Retest Due	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (kVA)	Leakage (mA)	Overall Status
FABRICATION COMPANY - CUTTING SHOP										
SF604351	415V SPLITTER DAMAGED CASE	19/02/16	19/02/17	F	S	S	S	S	S	FAIL
Total Appliances >										1
FABRICATION COMPANY - FAB SHOP										
SF603354	110V LEAD CAP-FLEX DAMAGED	10/02/16	10/02/17	F	S	S	S	S	S	FAIL
SF603448	415V WELDER DAMAGED FLEX	10/02/16	10/02/17	F	S	S	S	S	S	FAIL
SF603485	ADT POWER SUPPLY TWIN AND EARTH USED	10/02/16	10/02/17	F	S	S	S	S	S	FAIL
Total Appliances >										3
FABRICATION COMPANY - GENERAL OFFICE										
SF602315	IEC LEAD INSULATION FAILED 0.23MOHM	28/01/16	28/01/19	P	S	P 0.06	F 0.23	S	S	FAIL
Total Appliances >										1
FABRICATION COMPANY - MANAGING DIRECTOR										
SF602336	IEC LEAD TWO CORE CABLE, NO EARTH CORE	28/01/16	28/01/19	P	S	F >19.99	S	S	S	FAIL
Total Appliances >										1
FABRICATION COMPANY - PURCHASING OFFICE										
SF602231	ADAPTOR DAMAGED CASE	28/01/16	28/01/19	F	S	S	S	S	S	FAIL

APPLIANCE DETAILS AND TEST RESULTS

Key
P = PASS / F = FAIL / S = SKIP (or test not applicable)

Appliance Id	Appliance Description	Test Date	Retest Due	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (KVA)	Leakage (mA)	Overall Status
SF602233	LAMINATOR DAMAGED CASE	28/01/16	28/01/17	F	S	S	S	S	S	FAIL

Total Appliances > **2**

FABRICATION COMPANY - WORKS CANTEEN

SF603433	MICROWAVE RUST AND EXTERIOR DAMAGE	10/02/16	10/02/17	F	S	S	S	S	S	FAIL
----------	---------------------------------------	----------	----------	---	---	---	---	---	---	------

Total Appliances > **1**

Total Appliances For Report: 9